

019-Step 1.

OPERATION: INITIAL OXIDATION

TEMPERATURE: 1050°C

PROCEDURE:

| <u>STEP</u> | <u>PROCEDURE</u> | <u>SETTING</u> |
|-------------|--|----------------|
| 1. | Turn off Nitrogen | |
| 2. | Turn on Oxygen | 13 GL |
| 3. | Leave Oxygen on 15 minutes - <i>Purge</i> | |
| 4. | Remove end cap, attach elephant with wafers previously loaded onto ladder boat | |
| 5. | Push ladder boat into center hot zone, 5-10 seconds push | |
| 6. | Attach vented cap to exhaust - <i>@ snorkel?</i> | |
| 7. | After five minutes, turn off Oxygen, turn on O ₂ -HCl | 11.3 SS |
| 8. | After 40 minutes, turn off O ₂ -HCl, turn on Oxygen | 13 GL |
| 9. | After 5 minutes, withdraw boat into elephant via 10-15 second pull | |
| 10. | Remove elephant, replace end caps onto furnace tube and elephant | |
| 11. | Turn off Oxygen | |
| 12. | Turn on Nitrogen | 5.5 SS |

TEAM

Note: Step #2 is missing

6502

ORG

PHOTO RESIST STRIP - CAROSEQUIPMENT:

- 1) Hot Plate
- 2) 3000 ml beaker
- 3) Teflon boat and trigger handle

PROCEDURE:

- 1) Place 1500 ml of Sulfuric Acid onto hot place and heat to max. of 40°C.
- 2) Pour in 1500 ml of Hydrogen Peroxide.
(unstabilized) Providing temp is not above 40°C.
- 3) Check reaction temp for a minimum of 140°C.
- 4) Place wafers into caros for 15 minutes.
- 5) Remove work and place into 1st rinse tank for 2 minutes.
- 6) Move work to 2nd rinse tank for 5 minutes.
- 7) Super Q
- 8) Spin Dry

019 - Stage 4, 7, 33

OPERATION: PYROLYTIC OXIDE DEPOSITION (PACIFIC WESTERN MACHINE)

TEMPERATURE: $410^{\circ}\text{C} \pm 5^{\circ}\text{C}$ (By Thermocouple)

PROCEDURE:

| <u>STEP</u> | <u>PROCEDURE</u> | <u>SETTING</u> |
|-------------|--|---|
| 1. | Heat up machine with city water on | 13 SS |
| 2. | Turn Temperature controller to | ≈ 435 |
| 3. | Turn on Oxygen | 6.5 SS |
| 4. | Turn on Silane | 7 SS |
| 5. | Check Nitrogen flow rates* | N_2 10 SS N_2 9 SS |
| 6. | Check exhaust setting on magnehelic | 20-30 |
| 7. | When susceptor is up to temperature, load wafers 2 or 3 abreast (Maximum of 18 wafers per susceptor) | |
| 8. ** | Adjust speed setting to that required such that thickness specified is obtained with 1 pass of susceptor under gas distribution head | |
| 9. | Start susceptor scan | |
| 10. | Remove deposited wafers after susceptor stops | |
| 11. | When all wafers are deposited per 7-10, turn off Silane and Oxygen*** | |
| 12. | Turn off main power to machine | |

* For Bosphorus glass deposition, open fully dopant flow meter and set digital meter at 5.5 and 7.3 for Diborane (B_2H_6) and Phosphine (PH_3) respectively; these settings will result in dopant flow meter reading of ≈ 10 SS after 3-5 minutes purge.

** Speed settings are as follows for various glasses required:

| <u>REQUIREMENT</u> | <u>SETTING</u> |
|--|-----------------------------|
| 13 Mole% Bosphorus Glass (7500A ⁰) | ≈ 180 (2.3 in/min) |
| Undoped Pyro Overlay (6000A ⁰) | ≈ 190 (2.45 in/min) |
| Undoped Field Oxide (6000A ⁰) | ≈ 190 (2.45 in/min) |
| Undoped Oxide Mask for Nitride (2500A ⁰) | ≈ 300 (4.1 in/min) |

*** For Bosphorus glass deposition, turn off main Phosphine and Diborane cylinder valves, turn on Nitrogen purge valves, and purge minimum of 10 minutes before turning off machine.

019 Step (a) 5,III WAFER SCRUBBERMACHINE OPERATION:

(1) Fill pressure tanks

Tank I = FC-93 + H₂OTank II = DI H₂OTank III = IPA (*iso-propyl alcohol*)

(2) Press "ON" button

(3) Press "RECYCLE" button

(4) Insert Teflon boats into respective tracks

(5) Press "Auto Cycle" button & "Cycle Start" button

(6) Check cycle times & spin speeds:

Cycle I = 5" FC93+H₂O - 800 RPMCycle II = 3" DI H₂O - 800 RPM

Cycle III = 3" IPA - 800 RPM

Cycle IV = 5" Spin Dry - 6000 RPM

Daily Check Out:

Every morning machine is to be checked out by running 3 virgin wafers thru the complete cycle. Upon completion of scrubbing operation, the 3 wafers are to be checked out for dirt particulates under a collimated light source. If wafers are dirty notify supervisor immediately.

019 - Steps 6, 9.

OPERATION: FIELD OXIDE DENSIFICATION (019)

TEMPERATURE: 950°C

PROCEDURE:

| <u>STEP</u> | <u>PROCEDURE</u> | <u>SETTING</u> |
|-------------|---|----------------|
| 1. | Remove end cap, attach elephant with wafers previously loaded onto ladder boat | |
| 2. | Push boat into center zone, 5-10 second push | |
| 3. | Attach vented cap from elephant to exhaust | |
| 4. | Turn off Nitrogen, turn on O_2 -HCl | 5.5 SS |
| 5. | After 30 minutes, turn off O_2 -HCl, turn on Nitrogen | 5.5 SS |
| 6. | After 5 minutes, remove vented cap and withdraw boat into elephant via 5-10 second pull | |
| 7. | Remove elephant, replace end caps onto furnace tube and elephant | |

| PROCESS LEVEL | FILM | RESIST | PRE-BAKE (1) (9) | SPIN (2) | POST-BAKE (3) | APPROX. EXPOSURE | DEVELOP (4) | ETCH (5) | STRIP (6) | APPROX. ETCH TIME (7) | SPIN DRY (8) | TEST (9) | 3RD LIP (10) | 50-1 (11) | RINSE (12) | RINSE (13) | SUPER Q (14) | SPIN (15) |
|---------------------|---------|--------|------------------|----------|---------------|------------------|---------------------|-----------|---------------------|-----------------------|---------------|-----------|--------------|------------------------|------------|------------|--------------|------------|
| I X ₄ | DR 7402 | AR 302 | 30' / 180 | 5K | 30' / 200 | 6-11" | 30' / 80 SILICON | 30' / 180 | 30' / 80 SILICON | 45-5' / 45" | 2'-5' / 2'-5' | NO YES | CAROS NO | To Dewet 30' MIN | 2' | 5' | 15' | YES YES |
| II ACPLETIX | DR " | " | " | " | " | 10" | NONE | 15' / 180 | NONE | - | - | - | CAROS | 45" | 2' | 5' | 15' | YES |
| III POLY-90 | DR " | " | " | " | " | 10" | DIJ | 30' / 180 | DIJ | 45" | 2'-5' | YES | CAROS | 30" | 2' | 5' | 15' | YES |
| IV POLY-61 | LT " | " | " | " | " | 6-11" | GN5(8) DIJ | " | GN5(8) DIJ | 24-3' / 10" | 2'-5' | YES | CAROS | 30" | 2' | 5' | 15' | YES |
| V FUS QTRIC | DR " | " | " | " | " | 10" | DIJ | " | DIJ | 5' | 2'-5' | YES | CAROS | 30" | 2' | 5' | 15' | YES |
| VI METAL | LT " | " | " | " | " | 6-11" | PNA | " | PNA | 1-14' | 2'-5' | YES | J-100 | - | 2' | 5' | 15' | YES |
| VII OVERLAY | LT KTRP | " | " | " | " | 5" | PASS. | " | PASS. | 14' | 2'-5' | YES | J-100 | - | 2' | 5' | 15' | YES |

NOTES:

- (1) (3), (5) BAKES - TIME/TEMP (MINUTES/²CENTIGRADES)
- (2) ALL SPINS 50 SECONDS
- (3) A2 = DEVELOPER/RINSE/RINSE (DEVELOPER - 1 PART MF312 to 1 PART D.I WATER
- (4) KTRP: XYLENE/1:1/IPA + COROTEK DRYING
- (5) STRIPANTS:
 - RHF = 1000 ML RHF + 4 ML PCB (34°C ± 1°C)
 - 50-1 = 60 ML HF + 3000 ML H₂O (ROOM TEMP)
 - 10-1 = 200 ML HF + 2000 ML H₂O (ROOM TEMP)
 - SILICON = 2500 ML HNO₃ + 1000 ML CH₃COOH + 25 ML HF (5000 TEMP)
 - PNA = 3200 ML H₂PO₄ + 200 ML CH₃COOH + 200 ML H₂O + 400 ML H₂O + 5 ML FC-93 (35 ± 5°C)
- (6) (PASS. = 2500 ML RHF + 500 ML CH₃COOH + 50 ML FC-907
- (7) STRIPANTS: CAROS - HEAT 1500 ML H₂O to 40°C; ADD 1500 ml H₂O; CHECK TEMP 130°C; STRIP 15 minutes
- (8) 1-100 = 90-110°C 1-160 to min.; 5' 60°C XYLENE; 2' TCE; 2' Methanol
- (9) CAS RICH - FLOW 3.5, 450%, REFLECTED <20%
- (10) OPTIONAL IF DIRECT FROM FABRICE
- (11) 2' TANK #1; 2' TANK #2; TAG #3 to 120SL
- (12) 50-1 TO DRY

Step 12, 19,
24, 32, 39
44, 49

INSPECTION GUIDELINES

| PHOTO OPERATION | AFTER DEVELOP | | | | | | | AFTER ETCH | | | | | | |
|------------------|---------------|----------------|---------------------|--------------------|-----------|--------------------|--|--------------------|--------------|----------|---------------------|------------|----------------|---------------|
| | OVER EXPOSURE | UNDER EXPOSURE | PROPER MASK CONTACT | DEVELOPED PROPERLY | ALIGNMENT | MEASUREMENT REQ'D. | | MEASUREMENT REQ'D. | UNDERCUTTING | OVERETCH | CONTACT CLEARED OUT | SNOOP/AKES | BRIDGING METAL | LIFTING METAL |
| 1 - SOURCE DRAIN | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | ✓ | ✓ | | | | |
| 2 - DEPLETION | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | ✓ | ✓ | | | | |
| 3 - POLY - N* | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | ✓ | ✓ | | | | |
| 4 - GATE | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | ✓ | ✓ | | | | |
| 5 - PRE - OHMIC | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | ✓ | ✓ | ✓ | | | |
| 6 - METAL | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | ✓ | ✓ | ✓ | | ✓ | ✓ | ✓ |
| 7 - PASSIVATION | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | | | ✓ | ✓ | | | | |

SILICON ETCH (25-10)PREPARATION:

| | | | | |
|----|--------|-----------|---|--------|
| 1 | HF | - 25 ml | } | @ 34°C |
| to | Nitric | - 2500 ml | | |
| to | Acetic | - 1000 ml | | |
| 40 | | | | |

- (1) Insert 3 dummy wafers into a Teflon etch boat and etch for 1 hour before attempting to etch lot.
- (2) After etch has been primed, insert 6 good wafers into etch solution for 1'45".
- (3) Rinse and cut a sliver off of one wafer.
- (4) Strip in H.F., rinse, dry and measure etch step with dektac. If measurement falls between 1500-2500Å proceed to etch balance of lot - 6 wafers at a time. Note and record measurement on run sheet.
- (5) If measurement falls above or especially below the 1500-2500Å range--- notify supervisor immediately. DO NOT PROCEED WITH BALANCE OF LOT!